IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200207855-1

IN RE APPLICATION OF: U.S. Patent No. 7,174,470

USPTO CONFIRMATION CODE: 3994

APPLICATION NO.: 10/685,250

FILED: Oct. 14, 2003

EXAMINER: Lynne H. Browne

GROUP ART UNIT: 2116

FOR: COMPUTER DATA BUS INTERFACE CONTROL

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/685,250, now Patent Number 7,174,470.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

⊠ fee is 1	All errors were the fault of the USPTO, no fee required. In the event that a further required, please charge the amount to Deposit Account No. 082025.
	All errors were the fault of the applicant and, accordingly, please charge \$\frac{\\$100.00}{200.00}\$ Deposit Account No. 082025. In the event that a further fee is required, please the amount to the same Deposit Account.
•	The errors were the fault of both the applicant and USPTO and, accordingly, charge §100.00 to our Deposit Account No. 082025. In the event that a further fee tired, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 10, line 56, in Claim 16, delete "circuit;" and insert - - circuits; and - -, therefor.

(Amendment to claims filed on Jul. 14, 2006, page 5, in Claim 18, lines 14-17)

In column 11, line 62, in Claim 33, after "enabled by" delete "a". (Amendment to claims filed on Jul. 14, 2006, page 7, in Claim 37, line 2)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

November 6, 2009 DATE /David A. Plettner/ Name: David A. Plettner Registration No.: 36,241

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road, Mail Stop 35 Fort Collins CO 80528-9599

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

(Also Form PTO-1050)

PATENT NO. : 7,174,470

APPLICATION NO. : 10/685,250

ISSUE DATE : Feb. 06, 2007

INVENTOR(S) : Benjamin Thomas Percer, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 10, line 56, in Claim 16, delete "circuit;" and insert - - circuits; and - -, therefor.

In column 11, line 62, in Claim 33, after "enabled by" delete "a".

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado 80527-2400

This collection of information is required by 37 CFR 1.322, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.